ਦਫਤਰ: ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2,ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,ਹੁਸ਼ਿਆਰਪੁਰ।

ਈ-ਮੇਲ :- xen_c2@yahoo.co.in

ਵੱਲ.

Principal, Doaba Public Sen, Sec. School, Parowal, P.O. Garhshankar, District Hoshiarpur.

ਨੰ: 223

ਮਿਤੀ: 24/4/2025

ਵਿਸ਼ਾ:-

ਇਸੂ ਆਫ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ 2025-26

ਹਵਾਲਾ:

ਆਪ ਦਾ ਪੱਤਰ ਨੰ. DPS/MISC/2025-16244 ਮਿਤੀ 01.04.2025

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿਚ ਆਪ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.1, ਗੜ੍ਹਸ਼ੰਕਰ ਵਲੋਂ ਕੀਤਾ ਗਿਆ ਹੈ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋਂ ਠੀਕ ਲੱਗਦੀ ਹੈ ਅਤੇ ਸਾਲ 2025–26 ਲਈ (ਮਿਤੀ 24.12.2025 ਤੱਕ) ਸੁਰੱਖਿਅਤ ਸਰਟੀਫਿਕੇਟ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਤੇ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

- 1) ਬਿਲਡਿੰਗ ਦੇ ਆਲੇ–ਦੁਆਲੇ ਅਤੇ ਛੱਤਾਂ ਉੱਪਰ ਪਾਣੀ ਖੜ੍ਹਾ ਨਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
- 2) ਜੇਕਰ ਇਮਾਰਤ ਵਿਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਵਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤਰੁੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੇਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ।
- 3) ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇ ਤਾਂ ਉਸ ਨੂੰ ਨਕਸ਼ੇ ਵਿਚ ਮਾਰਕ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸਦਾ ਏਰੀਆ ਕੁੱਲ ਕਵਰਡ ਏਰੀਏ ਵਿਚ ਸ਼ਾਮਿਲ ਕੀਤਾ ਜਾਵੇ।

ਨੱਥੀ/ਨਕਸ਼ਾ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,

ਉਸਾਰੀ ਮੰਡਲ ਨੰ.2, ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ,

₹ਹੁਸ਼ਿਆਰਪੁਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ.

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.1, ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਗੜ੍ਹਸ਼ੰਕਰ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 24 ਮਿਤੀ 22.04.2025 ਦੇ ਹਵਾਲੇ ਵਿਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/ਨਿੱਲ।

ਕ੍ਰੇ) ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2, ਲੋ:ਨਿ:ਵਿ:ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਹਸਿਆਰਪਰ।

True translation from Punjabi to English

Office: Executive Engineer, Construction Division No. 2, Public Works Departmet B & M Branch, Hoshiarpur.

E mail:-xen_c2yahoo.co.in

To,

Principal. Doaba Public Sen, Sec. School, Parowal, P.O. Garhshankar, District Hoshiarpur.

No. 223

Dated 24/4/2025

Subject :

Issue of Building Safety certificate for the year 2025-26

Reference: Your letter No. DPS/MISC/2025-16244 dated 01.04.2025

In connection with the above subject, you are informed that the school building has been inspected by the Sub Divisional Engineer, Construction Sub Division No. 1, Garhshankar and the building appears to be in good condition and a safety certificate is issued for the year 2025-26 (upto 24.12.2025). Certificate issued under the following conditions:-

- Water should not be allowed to stagnate around the building and on the roofs.
- 2) Any kind of cracks etc. appears in the building, then that place should be vacated immediately and its repair should be dome immediately.
- 3) If you have any additional construction to do apart from the attached map, then it should be marked on the map and its area should be included in the total covered

Sd/- in Punjabi **Executive Engineer**

Attachment/Map

Construction Division No. 2. L.N.V, B & M Branch

Letter No.

Dated

OTAR

98145-25133

Madan Mahi

A copy of the above is sent to the Sub Divisional Engineer, Construction Sub Division Noi. 1, L.N.V B & M Branch Garhshankar for information with reference to his letter No. 24 dated 23.04.2025.

Attachment/Nil

Principal

Sd/- in Punjabi **Executive Engineer**

Construction Division No. 2. L.N.V, B & M Branch

Hoshiarpur

Attested True Photocopy Translation Copy of the Documents

NOTARY PUBLIC

Proshiatour (Pb.) India

Doaba Public Sen. Sec. School Parowal, P.O. Garhshankar, Distt. Hoshiarpur

1 3 MAY 2025